BRUHAT BANGALORE MAHANAGARA PALIKE

DASARAHALLI ZONE

Name of Work: Improvements to water supply schems in Sidedahalli Village area in Ward No-14

PART -A

Sl. No.	Particulars	Unit	No	L	B	D	Qty	Rate	Amount
1	2	3	4	5	6	7	8	9	10
	PART - A								
I	MOTOR REWINDING								
1	Repairs to Motor: Rewinding of submersible pumpsets with copper insulation wire of suitable guage as per ISI specification with guarantee of 6 months Page No-63, Item No-A(3) BWSSB SR2012-13	NO							
	a) 7.5 Hp Motor		4				4	3822.50	15290.00
	b) 10 Hp Motor		4				4	4785.00	19140.00
	c) 12.5 H P Motor		16				16	5855.00	93680.00
II	PUMP REPAIRS								
	Replacement of pump parts the following main components of submersible pumpsets requiring replacement								
2	Pump bowls Page No-63, Item No-B(1) BWSSB SR2012-13	No.							
	a) 7.5 Hp Motor		30				30	308.00	9240.00
	b) 10 Hp Motor		60				60	308.00	18480.00
	c) 12.5 H P Motor		80				80	308.00	24640.00
3	Intermediate piece (I.P) with leaded bronze bush Page No-63, Item No-B(2) BWSSB SR2012-13	No.							
	a) 7.5 Hp Motor		4				4	715	2860.00
4	Oil seal Page No-63, Item No-B(3) BWSSB SR2012-13	No.							
	b) 10 Hp Motor		6				6	121.00	726.00
	c) 12.5 H P Motor		16				16	121.00	1936.00
5	Oil seal steel bush Page No-63, Item No-B(4) BWSSB SR2012-13	No.							
	b) 10 Hp Motor		2				2	132.00	264.00
	c) 12.5 H P Motor		18				18	132.00	2376.00
6	Guide vane Page No-63, Item No-B(5) BWSSB SR2012-13	No.							
	b) 10 Hp Motor		80				80	192.50	15400.00
	c) 12.5 H P Motor		30				30	192.50	5775.00
7	Impeller (shell moulded with aluminium and bronze) Page No-63, Item No-B(6) BWSSB SR2012-13	No.							
	b) 10 Hp Motor		40				40	264.00	10560.00
	c) 12.5 H P Motor		60				60	264.00	15840.00